



**INTEGRA96 ULUSLARARASI URUN VE SISTEM
BELGELENDIRME, BAGIMSIZ GOZETIM, DENETIM, EGITIM
HIZMETLERI LTD. STI.**

Girne Bulvarı No:186/2 Karşıyaka / İzmir - TÜRKİYE
Tel: +90 232 462 20 51-52 Faks: +90 232 462 20 61
info@integra96.com www.integra96.com

2006/42/EC CONFORMITY REPORT

EN ISO 12100:2010

**Safety of machinery- General principles for design-
Risk assessment and risk reduction (ISO 12100:2010)**

Manufacturer	İROTECHARGE TAS. YZL. ELE. ELEKTR. İNŞ. MADEN TAAH. EML. TUR. İTH. İHR. SAN. VE TİC. LTD.ŞTİ.		
Adress.....	Muslihittin Mah. Akyol Sok. No: 2 / 7 Altınay Apt. Menteşe / Muğla / TÜRKİYE		
Product / Model(s)	Su Altı Görüntüleme Sistemi – SGS Underwater Imaging System – SGS		
Report Number	TRM-21-2299/02		
Date of issue.....	19.04.2021		
Standard	EN ISO 12100:2010		
Number of pages (Report).....	08		
Number of pages	-		
Compiled by.....	Eng. C. HURŞİTOĞLU	Approved by.....	Eng. C. TAHİR
(+ signature)		(+ signature)	
test case does not apply to the test object.....			N/A
test object does meet the requirement.....			P(ass)
test object does not meet the requirement.....			F(ail)
General Remarks			

"(see remark #)" refers to a remark appended to the report.

"(see appended table)" refers to a table appended to the report.

Through out this report a comma is used as the decimal separator.

This report shall not be reproduced except in full without the written approval of the testing laboratory.